

auto-com

אדיר מכון רישוי ובדיקה

Address: שבזי 8 יהוד
Postal address: 56000
Phone: 03-5366678
E-mail: TESTADIR@GMAIL.COM

Mechanic: נגר יובל
Date: 10/12/2021
Car licence no: 563-92-101
VIN: JF1SJ5LC5JG374595
Mileage: 24294KM
Vehicle: Subaru - Forester [13-] - 2018

Fault codes

Engine electronics

DTC	Description
P0852	- Park / Neutral Switch Input Circuit High
P0031	- Oxygen (Air/Fuel) Sensor Heater Control Circuit Low (Bank 1 Sensor 1)
P2102	- Throttle Actuator Control Motor Circuit low
B1572	- IMM Circuit Failure (Except Antenna Circuit)

Brake (ABS (Antilock braking system) - ABS/VDC)

DTC	Description
C1424	- ECM abnormal

Instrument (Instrument - Diagnose)

DTC	Description
U0151	- Lost communication with SRS airbag ECU
U0131	- Lost Communication with Electronic Power Steering Control Module
U0122	- Lost communication with brake system control module

מכון אדיר בטיחות
ח.ב. 513603100

Climate (HVAC (Heating Ventilation Air Conditioning) - HVAC (Heating Ventilation Air Conditioning))

DTC	Description
B14A1	- Sunload Sensor Circuit Open

Gearbox (Gearbox - Diagnose)

DTC	Description
	No fault codes

Restraints (Airbag - Diagnose)

DTC	Description
B1650	- ODS (Occupant detection system) failure

Multifunction (Body computer - Diagnose)

DTC	Description
B1402	- Immobilizer key collation NG
B1411	- Immobilizer antenna abnormal
U0122	- Nonarrival of H-CAN data(VDC)
U1500	- Keyless UART communication malfunction

Multifunction (Electrical power steering - Diagnose)

DTC	Description
	No fault codes

Multifunction (Occupant detection system - Diagnose)

DTC	Description
	No fault codes